



Stencil Pavement Repair

Technical Bulletin 0105



The first picture on the left displays the damaged slatecrete stamped concrete driveway. As a result of a motor vehicle accident, rubber burn marks had been burnished into the top coating system causing the colour to be removed back to the base concrete underneath.

As the slatecrete continued up a side pathway and around to the backyard it was important that the repair at the front matched the existing rear slatecrete.

As seen in the centre picture, the driveway topcoats and rubber tyre marks were removed using the Graffiti Eaters surface restoration technology and the surface thoroughly prepared for recoating.

Using a blend of releasing agents and pigments, a coating system was then devised to colourmatch the slatecrete effect, and repair the driveway. The shadowing highlights and translucency of this particular colour made it a challenging match to achieve.

The end result was a perfect repair that blended in with the backyard, tyre mark free, at a fraction of the cost of ripping up and relaying a new driveway, saving this insurance company significant costs.

If you have a similar cleaning challenge, or would like to know more about the 'Hard Surface Restoration' jobs we perform, give us a call, or check out our website below.

www.graffitieaters.com

